


# Negative Pressure Canon Model 500 Uplift Chamber

Building Code: TAS-124



## CONTACT OUR TEAM

[www.paramountce.com](http://www.paramountce.com)  
[info@paramountce.com](mailto:info@paramountce.com)

### MIAMI

6135 NW 167th Street  
Suite E-1, Miami, FL 33015  
P. 305.698.0550  
F. 305.698.0558

### TAMPA

100 South Ashley Drive  
Suite 600, Tampa, FL 33602  
813.397.3635



# SPECIALIZED TESTING





# Pull Off Test

Standard: ASTM C1583



# Pull Test

Standard: ASTM C1860-21



# Impedance Roof Moisture Surveyor

Standard: ASTM D7954/D7954M-15a



# Infiltration and Duct Leakage

FL Building Code: Form R405-2017



# Posi Test Air Leak Tester

Standard: E1186-22

